

Revision Record

| Date | Version | Revision |
|------------|----------------|---|
| 1/13/2025 | 1.0.0.2.13 | 1. Add gain compression measurement and vector mixing measurement function |
| 5/28/2024 | 1.0.0.2.12 | 1. Add material measurement function option 2. Add switch matrix expansion multi-port application options |
| 11/29/2023 | 1.0.0.2.11.R6 | 1. Add manual configuration of DC under TDR 2. Add calibration overwrite function 3. Optimize synchronization of external triggers for pulse measurements |
| 9/22/2023 | 1.0.0.2.11.R1 | 1. Fixed the range limits for frequency and power in mixer measurements 2. Fixed the trace title bar color to match the memory trace color |
| 7/10/2023 | 1.0.0.2.11 | 1. Added Pulse modulation function |
| 3/2/2023 | 1.0.0.2.10.R10 | 1. Added user manual calibration and verification function (option) 2. Added the function that the number of vertical grid can be set 3. Added the function of supporting logarithmic display of vertical coordinates 4. Added point limit function |
| 11/11/2022 | 1.0.0.2.10.R9 | 1. Added scalar mixer measurement function 2. Adjusted and optimized the spectrum analysis measure interface |
| 9/30/2022 | 1.0.0.2.10.R8 | 1. Added Freq Offset function 2. Optimized some functions of spectrum analysis 3. Added status bar to display smooth status 4. Added advanced mode for bandwidth search, support frequency percentage bandwidth setting function 5. Optimized the Marker->Delay algorithm |
| 7/5/2022 | 1.0.0.2.10.R5 | 1. Added independent configuration function of emission source in spectrum mode 2. Optimized the sweep process 3. Optimized TDR interface 4. Added command for transferring file data 5. Added marker->SA commands |

| Date | Version | Revision |
|------------|--------------|---|
| 3/29/2022 | 1.0.0.2.10 | <ol style="list-style-type: none">1. Added spectrum analyzer option2. Fixed input bug in network configuration window3. Fixed mouse click input box crash bug4. Increased the touch-sensitive area of the DHCP checkbox5. Modified the policy when the DHCP request fails |
| 12/29/2021 | 1.0.0.2.9.R5 | <ol style="list-style-type: none">1. Solved the menu button is not updated when the electronic calibration module is inserted or removed2. Fixed a bug that the touch screen may crash under some cases3. Fixed an option installation bug |
| 11/25/2021 | 1.0.0.2.9 | <ol style="list-style-type: none">1. Added some SCPI commands2. Solved memory leaks and crashed in some cases |
| 9/28/2021 | 1.0.0.2.8 | <ol style="list-style-type: none">1. Add shortcut buttons at the toolbar2. Fix the stuttering problem when adjusting the brightness of the grid in the waveform area3. Solve the problem of probabilistic crashes when opening dialogs4. File storage shortcut keys support more types5. Support more power meters6. Add picture editing function to the screenshot dialog7. Adds peak reference function for bandwidth search8. Modify the contents of the Chinese and English help files9. Modify the user receiver calibration process10. The input box will pop up automatically when using the toolbar button to add Marker |