

## Revision History

Date	Version	Revision
2023/4/25	5.01.01.09R2	<ol style="list-style-type: none"> <li>1. Add and optimize the manual calibration function</li> <li>2. Solve the socket communication in multiple cycles of open/close, may not respond to the problem</li> <li>3. Fix the problem that the "READ" command does not match the description in the programming manual</li> <li>4. Fix the key test screen no prompt</li> <li>5. Optimize the connectivity test buzzer response speed issues</li> </ol>
2021/9/22	5.01.01.07R1	<ol style="list-style-type: none"> <li>1. Add the customer sensor support.</li> <li>2. Add the manual calibration support.</li> <li>3. Optimize flash R&amp;W design.</li> <li>4. Fix some UI &amp; SCPI bugs</li> </ol>
2021/2/5	5.01.01.06R1	<ol style="list-style-type: none"> <li>1. Fixed some unit faults in 06version</li> <li>2. Fixed some bugs about communication with easysdm.</li> </ol>
2021/1/8	5.01.01.06	<ol style="list-style-type: none"> <li>1. Fixed some crash fault about U disk save&amp;recall.</li> <li>2. Fixed some bugs about "acquire" function.</li> <li>3. Improve the trend display function.</li> <li>4. Update the software platform code.</li> </ol>
2019/4/23	5.01.01.05	<ol style="list-style-type: none"> <li>1. Change the size of text in dual display mode.</li> <li>2. Added customer defined time base in the trend diagram.</li> <li>3. Enhanced the volume of buzzer.</li> <li>4. Bug fix: The screen saving setup was lost after power cycle/reboot.</li> <li>5. Moved CSV file save function from the utility page to the acquire page.</li> <li>6. Added recording measurement data to external U disk.</li> </ol>
2017/6/06	5.01.01.03	<ol style="list-style-type: none"> <li>1. Add U disk recovery function.</li> <li>2. Modify Hold function arithmetic.</li> <li>3. Add the telnet SCPI function; port is 5024</li> <li>4. Example: telnet 192.168.0.10 5024</li> </ol>