

Revision History

Date	Version	Revision
2/1/2018	5.01.01.15R5	<ol style="list-style-type: none">1. Optimized PLL configuration2. Fixed several bugs<ol style="list-style-type: none">a) Enabling Mod on CH2 may disable Burst on CH1b) Duty cycle error on Square wave with very long periodc) SCPI command cannot adjust the phase difference between two synchronized unitsd) Manual trigger cannot trigger both channels simultaneously
11/11/2015	5.01.01.15R1	<ol style="list-style-type: none">1. Supported bandwidth update option (Note: The option will be only available on the hardware after Jan. 1st, 2016)2. Added channel coupling function3. Fixed miscellaneous minor bugs